

TS 1500




101827-10

**GEZE**




10 mm

**A**




$a \leq 1100 \text{ mm}$

**B**




$a \leq 1100 \text{ mm}$


EN 3/4

















EN 3/4



EN 2




EN 2





4x  
M5x34



**1**



**2**




**3**




4

a = 950 - 1100 mm (EN 4)




a < 950 mm (EN 3)

a < 850 mm (EN 2)




a = 950 - 1100 mm (EN 4)




a < 950 mm (EN 3)



a < 850 mm (EN 2)





5





6




7




8




i




EN 3/4




EN 3/4




EN 2




EN 2




EN 3/4



EN 3/4



EN 2



EN 2

