







Ax1 	Hx4  M6x20 SCREW
Bx1 	Ix4  M6x25 SCREW
Cx1 (L) x1 (R) 	Jx4  M8x40 SCREW
Dx1 	Kx4 
Ex1 	L M6x1 
Fx1 	
Gx5 	

