




9



13.11.2019




Инструкция по сборке

10




Короб для постельных принадлежностей
 048-41
 H30XL


край короба





край короба









8




6



7

















M 1:1

- M4пш
x2
- M6
x4
- Ш6
x4
- 4x16
x6
- Ш8пласт
x2
- M8с
x2





- Ш8
x2
- 4,2x19
x4
- M4x20
x2
- M6x25
x4
- 7x50
x12
- M8x45
x2




5




M 1:1




1



2



3



4

