










GALANT




Design and Quality
IKEA of Sweden





118331

12x



101350

8x




101345

2x



119253
118137

8x




121762

8x




109503

12x




119030
117434

1x




130887

4x




130885

4x




146680

4x



158450
158451

1x




158452
158453

2x




139237

2x




100006

1x




158448
158449

2x




100347

4x




1x

158597
158599




122166

4x





150578

2x




122167


6x




1




2




3




4




5




6




7




8




9




10




11





12




13




14




346679





346683






346682












17



18




19






1x



158450
158451




1x

139237

158450
158451

100006


1x




100006

139237


158452
158453





20




21




22




4x




23




2x





25



26

